

Asbestos • Lead Paint • Mold • Indoor Air Quality • Industrial Hygiene

November 18, 2021

Town of Newbold
 c/o Dave Kroll
 PO Box 1063
 Rhinelander, WI 54501

Project:	Pre-Renovation Asbestos Sampling
Work Area:	Town of Newbold 4608 Apperson Drive Rhinelander, WI 54501
Site Date:	November 11, 2021
NorthStar No:	210-994

NorthStar Environmental Testing, LLC (NorthStar) was authorized by Dave Kroll on behalf of Town of Newbold to perform bulk sample collection and analysis for the presence of asbestos within the following material samples:

Sample ID	Bldg. Level	Material Location	Material Sample	Description	Asbestos Content
994-1	1	Men's Bathroom	Floor Tile Adhesive	Off-White	None Detected
994-2	1	Men's Bathroom	Floor Tile Grout	Gray	None Detected
994-3	1	Meeting Room	Vinyl Sheet Flooring	Brown	None Detected
994-4	1	Meeting Room	Vinyl Flooring Adhesive	Yellow	None Detected


Samples with a confirmed analysis of greater than one percent (>1%) are to be considered an asbestos containing material (ACM) and require special handling and disposal measures.

Laboratory Info:	Eurofins CEI, Inc. NVLAP# 101768-0		
Analysis Date:	November 17, 2021 (Reported)		
Collected By:	Marshall Kaiser (All - 276163)	Date:	November 11, 2021

Bulk sample analysis by polarized light microscopy with dispersion staining; USEPA method: EPA 600/M4-82/020 & EPA 600/R-93/116 (where applicable); Reported percentages are visually estimated by volume. Unless otherwise requested by client, each material or layer of a non-homogeneous sample is analyzed separately with reported percentages based on total sample. This report is not to be used to claim of product endorsement by NVLAP or any other U.S. Government agency.

Submitted By,

NorthStar Environmental Testing, LLC.



Marshall Kaiser
 Project Technician